HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

TREMONT STATION BRIDGE

(N.Y.N.H.&H.R.R. Boston-Provincetown Bridge No. 45.38)

(Pierceville Road Bridge)

Pierceville Road, spanning Conrail tracks

Wareham

Plymouth County

Massachusetts

Martin Stupich, Photographer, August 1995, except as noted.

General view of site from track bed. View to east. MA-141-1

General view of site showing abutments and water main spanning tracks. MA-141-2 View to east.

MA-141-3 Bridge approach from south end of roadway. View to north.

South abutment. View to southwest. MA-141-4

View across railroad right-of-way, showing north abutment and new concrete MA-141-5 bridge seat. View to north.

General view of inner face of west truss leaning against north abutment (note MA-141-6 scale at center vertical). View to north.

Closer view of west truss, showing one of two center panels with diagonal MA-141-7 counters. View to north.

MA-141-8 Closer view of west truss, showing two end panels. View to northwest.

Closer view of west truss, showing configuration of diagonals, verticals and -MA-141-9 lower chord members. View to northeast.

Closer view of outer face of east truss deposited on hillside east of crossing, MA-141-10 showing two end panels. View to northeast.

Detail of west truss, showing upper chord connection. View to north. MA-141-11

MA-141-12 Detail of east truss, showing upper chord connection at hip joint. View to northwest.

MA-141-13 Detail of east truss, showing upper chord connection to outrigger, vertical post and diagonal eyebar. View to northeast.

Detail of east truss, showing cast iron number plate on inclined endpost. View MA-141-14 to east.


HAER No. MA-141


HAEK MASS, 12-11/ARH. 3-

INDEX TO PHOTOGRAPHS TREMONT STATION BRIDGE (N.Y.N.H.&H.R.R. Boston-Provincetown Bridge No. 45.38) (Pierceville Road Bridge) HAER No. MA-141 (page 2)


MA-141-15	Detail of upper side of east truss at bearing point, showing pin connection and curved plate which was part of roller bearing assembly. View to northeast.
MA-141-16	Detail of lower side of east truss at bearing point, showing lower chord attachment to endpost. View to west.
MA-141-17	Detail of lower chord of east truss, showing pin connection through eyebars and U-bolt hangers from which floor beams hung. View to northwest.
MA-141-18	Detail of lower chord of west truss, showing pin connection through lower chord assembly, diagonal eyebars and vertical posts. View down and to east.
MA-141-19	Detail of lower chord of east truss, showing pin connection through lower chord assembly and U-bolt hangers. View northwest.
MA-141-20	Detail of lower chord of west truss, showing pin connection through lower chord assembly, hip verticals and U-bolt hangers.
MA-141-21	Detail of east truss, showing outer end of outrigger sway braces which fastened to outer ends of floor beams.
MA-141-22	View of two of original five floor beams on ground near south abutment. View to east.
MA-141-23	Detail of outer end of floor beam, showing anchor brackets for lower lateral

KEY TO PHOTOGRAPHS TREMONT STATION BRIDGE (N.Y.N.H.&H.R.R. Boston-Provincetown Bridge No. 45.38) (Pierceville Road Bridge) HAER No. MA-141 (page 3)





WEST TRUSS DETAILS



EAST TRUSS DETAILS